

## REFINEMENTS & DEFECT FIXES

- **Bluetooth Connection** – Updated Bluetooth connection process to address random disconnections
- **User Interface Updates** – various updates to the user interface to address display issues.
- **Hemisphere S320** – Resolved issue with UHF radio configuration
- **Sanding T7 radio configuration** – Resolved an issue with configuring Farlink protocols
- **Raw File Export** – updated raw file export to address formatting issue
- **App optimization** – optimized application to address memory leaks discovered.
- **GNSS Survey Report** – Addressed issue with local times showing incorrect dates.

## NEW AND UPDATED INSTRUMENT DRIVERS

### GNSS

- **GeoMax Zenith 60** - Added driver support

### Total Station

- **CHC CTS-1124R4** – Added new driver
- **E-Survey E3** – Added new driver
- **GeoMax Zipp20** - Added new driver
- **GeoMax Zoom 10/20/25/35/50** - Added new driver

## KNOWN ISSUES

- **ComNav N5** – Issue observing tilt enabled measurements.
- **Foif A90** – Issue configuring UHF radio
- **Stonex R20** – Issues with storing correct horizontal distances
- **Stonex R35/R2W** – Bluetooth connection issues
- **Configuring GSM RTK Corrections** – Some receivers may have issues with configuring RTK corrections via GSM.
- **Pentax SMT 888 3G** - Issue configuring digital UHF radio.